


1

拓普联科

TOP-LINK

6. HARMFUL MATERIAL CONTROL FOLLOW "ROHS"

DIMENSIONS IN MM
TOLERANCES UNLESS
OTHER SPECIFIED

0	=	$\pm -$
0.0	=	± 0.15
0.00	=	± 0.10
ANGLE: -13°		

CUSTOMER DRAWING FOR 5. 0H, 3. 0W, ANTENNA CLIPS

REMOVE BURRS, BREAK
SHARP EDGES R0.10 MAX
DO NOT SCALE PRINT

SCALE	DWG	SHEET	REV
1:1	ND.	1 OF 1	A1

PAD OF PCB

POINT OF MEASUREMENT

RECOMMEND PCB LAYOUT
TOLERANCE=±0.05

4

၆

2

1

A

w

9

D